Approved For Release 2008/03/07 : CIA-RDP78B04558A000700110057-1

Declassification Review by NGA/DoD

, 5

1963 AUG 31 O1 04Z

OUT51758

CJS 266

DHS

ACC

Grace (File)

P 382251Z

FM CIA VASNDC

TO RUCSER/SAC OFFUTT AFB, ONAMA, MEB

RUCVAB/4888 STRAT V8, OL 19, BARKSDALE AFB, LA

REEAHO/DIAXX

REECYS/MAYY PIC

RWBKG/15TH AF, MARCH AFB, RIVERSIDE, CALIF

RUNGAA/2D RTS, BARKSDALE AFB, LA

RUVGAA/2AF, BARKSDALE AFB, LA

DA GRNC

BT

CITE CIA-Z-848

SECRET

15TH AF (FOR DI); SAC (FOR DIN, BRASS KNOB, DOCR, DH 4), 2D AF (FOR DI). FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

- 1. CAMERA B-11 WAS USED IN MISSION 3785 FLOWN ON 29 AUG 63; PROCESSING WAS ACCOMPLISHED BY BARKSDALE.
 - 2. ORIGINAL NEGATIVE:
 - A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.
- B. 9R SIDE: A LONGITUDINAL EMULSION SCRATCH 4.35" FROM THE IMBOARD EDGE OCCURS INTERMITTENTLY THROUGHOUT THE ENTIRE MISSION AS EXEMPLIFIED BY FRAMES 2232 TO 2248, AND 1599 TO 1622. THE POSITION IMBICATOR LIGHTS ARE GHOSTED THROUGHOUT; AND MANUFACTURING SPLICES, WITH ASSOCIATED STATIC, PINHOLES, ETC., ARE LOCATED ON FRAMES 1679 AND 793.
 - C. 9L SIDE: FRAME 593 CONTAINS A 18" LONG AND 6.3" WIDE

GROUP 1
Excluded from automatic dewngrading and declassification

CEODET

Approved For Release 2008/03/07 : CIA-RDP78B04558A000700110057-1

CHENICAL STAIN. THERE IS A MANUFACUTURING SPLICE ON FRANE 2165 WITH ASSOCCIATED CREASES ON THE FOLLOWING TWO FRANES.

- D. BOTH SIDES: CONTINUOUS BUT HINOR PROCESSING STREAKS OCCUR THROUGHOUT AND THE HETERING IS SLIGHTLY ERRATIC. THERE ARE 2449 TITLED FRAMES ON EACH SIDE.
- E. NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING PROBLEMS OCCURRED IN THE MISSION.
 - 3. POSITIVE:
- A. PI SUITABILITY IS GOOD AND THE PRINTING AND PROCESSING OF THE DUPLICATE POSITIVE WAS GOOD.
- B. CLOUDS OBSCURED ABOUT 25 PERCENT OF THE TAKE.
 SECRET

END OF MESSAGE

(ABOVE MESSAGE ALSO PASSED TO CIA WATCH (ASP/RR))